Licensees Compliance Assessment Report - Aggregate Resources Act									
Background Information Year: 2018									
Licensee: St. Marys Cement Inc. (Canada)							ce ID #: 624984 Codrington Pit MNR District/Area Office: Peterborough		
Lot: Pt. Lots 32-34 Conc.: 6 Geographic Twp.: Murra			ray				Municipality: Mun. of Brighton		
					. (วbserv	vations		
		ATING STATE) PDC	IN C	OMPLIAN	ICE?		MENTS	Remedial
		ATING STANDA	-w-	Yes	No	N/A	CON	AMENTS	Action?
A - :	Site Access						·		Υ
A1 Boundaries (clearly marked)			✓		demai	ng completed at boundary of West Parcated as fence installation is offset fr stakes at comers of East Parcel and	rom boundary to preserve tree line.		
A2	A2 Entrance and Exits (location/closed)			✓		Off-site entrance for aggregate haulage at County Road 30 is gated. Farm access at Conc. 5 & 6 Road Allowance (Ferguson Hill Rd.) is also gated. Permanent entrance to West Parcel for aggregate haulage has been gated and gates installed at access road at north limit of hydro easement. Gates installed at West Parcel at location of proposed access between West and East Parcels.			
А3	Lease/Ownership/Ex	traction Agreem	nent			Owne	rship		
B - :	Site Protection								1
В4	B4 Fencing			✓		See A1. Fencing at south and east boundary of West Parcel is off-set from boundary to interior of site except where fence connects with West Parcel gate at point of proposed access between West and East Parcels.			
B 5	Fencing (site plan variation or temporary relief granted)		1		Ĺ	East Parcel to be fenced prior to extractive operations (not required at this time			
В6	6 Screening (trees/berms)		✓		West Parcel: Noise mitigation berms at southwest corner, south boundary and interim berm to west of active extraction area (see C10). Berm at east boundary is for topsoil storage only. East Parcel: No berms required at this time.				
B7 Setbacks (15m / 30m or other)			1		Setbacks are in place.				
C -	Operational Deta	ils			_				
C8 Operating Sequence			✓		Excav	nase 1, West Parcel.			
C9	C9 Stripping (overburden)			1		Overb	er agricultural fields in Phase 1 has onstruction, respectively.		
C10	C10 Overburden Seeded		✓		Overburden placed in vegetated berms.				
C11	C11 Extraction Depth		✓		Extraction (at max. depth) is permitted to +/- 155 m (asl). Lowest floor elevation +/- 181 m				
C12	C12 Buildings/Scales (location)		✓		None proposed. Shed to accommodate pump used in wash plant process. Scales, scalehouse / office are off-site at County Road 30 entrance.				
C13	C13 Equipment (any specific conditions or restrictions)		✓		Five loaders in operation (shipping/extraction/plant supply), 2 under repair, 1 shovel (extraction), 2 'pit trucks'.				
C14	C14 Plant (location/any specific conditions or restrictions)		✓		Portable wash plant, crushing plant and screening plant at Phase 1 northcentral pit excavation. Inactive screening plant at Phase 1 southeast pit excavation.				
C15	C15 Scrap (location/removal)		1		Scrap is removed on an ongoing basis.				
C16	C16 Stockpiles (location)		✓		Stockpiles In extraction area at Phase 1.				
C17	C17 Topsoil (location/seeded)		✓		Topsoil stripped from agricultural fields used in berm at east boundary.				
C18	8 Excavation Faces		✓		Multi-	Multi-lift excavation ongoing in extraction areas as per C8.			
C19	Ponds (location/de	Ponds (location/depth)				✓	Source and settling ponds built for portable wash plant.		
C20) Internal Roads (any	nternal Roads (any specific conditions or restrictions) / Internal re		nal roads for site preparation and hau	ılage of material off-site.				
C21	C21 Haul Routes (external/any specific conditions or restrictions)		✓		Off-site aggregate haulage is via north boundary of West Parcel, across hydro easement and through licensee owned lands including adjacent Archer Pit to County Road 30. Signs at 2 locations advising of public road haul route.				
C22	2 Blast Monitoring Re	eport (quarries o	nly)			✓			
C23	3 Dust Suppression			1			pressant to be used as necessary.		<u> </u>
C24	4 Hours of Operation (any specific conditions or restrictions) Operational activities are in accordance (Mon. to Fri. / 7 am to 7 pm).								
C25	5 Well Monitoring Re	5 Well Monitoring Reports Groundwater level monitoring / reporting is carried out.							
C26 Identification Sign (as per Sect. 5.22 of Provincial Standards)		✓		Signs installed at three locations: i) County Road 30 off-site entrance; ii) West Parcel entrance at hydro line; iii) Ferguson Hill Road farm field access at Conc 5 & 6 Road Allowance (West Parcel). Signs will be installed at accesses between East and West Parcel when inter-parcel access is established.					
C27	7 Orderly Conditions			1					
C2	8 Blasting Hours (qu	arries only)				1			

OPERATING STANDARDS	INC	OMPLIA	NCE?	E? COMMENTS			Remedia
	Yes	No	N/A			<u> </u>	Action
) – Rehabilitation				<u> </u>			Y
29 Disturbed Hectarage	√		Curren	t year - # of hectares	5.0	Total # of hectares 27.0	
30 Progressive rehabilitation	1		Curren	t year - # of hectares	0.0	Total # of hectares0.0	
D31 Sloping of Faces			Not required at this time.				
32 Grades/Contours/Elevations	1		Not re	Not required at this time.			
33 Importation of Material (inert)	√		No im	No importation of fill for rehabilitation purposes.			
D34 Vegetation			Former agricultural lands at northwest part of the West Parcel (non-extraction area) have been re-vegetated and planted with conifer nursery tree stock.				
D35 Final Rehabilitation			Not required at this time.				
- Prescribed Conditions (For Licences issued after	June 27	, 1997)	<u> </u>				<u></u>
E36 Other Monitoring Reports			Noise Monitoring Program as per Environmental Noise Monitoring Program & Complaint Procedure (Aercoustics, Feb. 24/13): Monitoring event was undertaken when extraction moved to southeast portion of West Parcel.			ercoustics, Feb. 24/13): Monitoring	
E37 Requirements of C of A's			Portable processing plants have operated this year in 'below grade' locations.				
E38 Noise Mitigation				Noise mitigation berming has been constructed in accordance with approved site plan and site plan amendment for interim berm (see B6 and page 5 sketch).			
E39 Fuel Storage Tanks				No permanent fuel storage on-site. Fuel tank associated with portable processing plant.		Fuel tank associated with portable	
E40 Spills Plan			Corporate plan is in effect.				
E41 Permit to Take Water			Permit issued for taking from two source water wells and pond.			ource water wells and pond.	
42 Dust Suppression Measures Req'd. (Haul routes, equip, etc.)	✓			Suppressants use	d as required.		
- Other Conditions (As indicated on either Site Plan or Lice	ence)						
Tonnage Condition	Fonnage Condition 650, 000 tonnes per annum (including up to 50,000 tonnes of material that may be imported for blending purposes).						
F44 Community Liaison Group (CLG)			Public meeting held on April 10, 2014 in Codrington to organise CLG. Subsequent correspondence with interested community members has occurred. Most recent CLG meeting was held on April 25, 2018.				
F45 Alternate 'back-up' warning devices			CBM has investigated alternative warning devices for use on CBM-owned equipment. Documentation of same has been provided to Municipality.				
F46 Complaint Response Procedure (Noise)			1 noise complaint received in June 2018. CBM's internal 'Contact Record Form' was used to document the complaint and follow-up, which is equivalent to Complaint Form as per Environmental Noise Monitoring Program & Complaint Procedure (Aercoustics, Feb. 24/13).				
F47 Natural Environment Report			in pla Plant	Installation of butternut tree protection fencing at south setback, West Parcel, in place. Planting of conifer trees at edge of forested areas that are to be retained (i.e. in excavation setback or non-extraction area) has been completed.			
F48 Archaeological Assessment and Ministry of Tourism, Culture and Sport comments			been Mark adjad extra dema	<u>Buffer zone demarcation:</u> Archaeological sites are demarcated and have not been impacted by pit operations. <u>Markers at limit of extraction prior to extraction activities:</u> extraction limits adjacent to the archaeological sites will be demarcated prior to aggregate extraction occurring adjacent to the sites. Sites themselves have been demarcated. <u>Worker training program:</u> instruction has been provided to workers.			- ;
F49 Visual Impact Assessment			Input from adjacent residents on berm construction: Discussions occurred p to construction with homeowner who responded to request (McNichol). Variations in berm height / slope / orientation subject to noise mitigation requirements: Berm at southwest corner of West Parcel has been built with horizontal curve and final shaping. Tree / shrub planting plan with input from adjacent residents: Planting has to place with input from McNichol. Other resident (Ferguson 'Estate') did not respond.		nded to request (McNichol). on subject to noise mitigation West Parcel has been built with a diacent residents: Planting has taken		
General Comments:							

THIS SECTION MUST BE COMPLETED WHEN REMEDIAL ACTION IS REQUIRED								
OPERATING STANDARDS from Pg. 1 (e.g. B4 – Fencing)	Remedial Action Required	Deadline Date	MNR Direction (for MNR use only)					
EXAMPLE B4 - Fencing	200 ft of West boundary to be fenced	June 15 / 99						
SEE NOTES BELOW REGARDING REMEDIAL ACTION DEADLINE DATES								
			·					
Sketch Included? (see note below	Licence ID #: 624984 Codrington Pit	Additional Detailed Information Attached						

- You must provide a sketch if remedial action is required or progressive rehabilitation has been performed.
- In order to extend the 90-day remedial action deadline date, you <u>must</u> obtain the Aggregate Inspector's approval (in writing) <u>prior to filing the report</u> with the Inspector or local MNR office.

Date Submitted to Y / M / D	MNR: 2018 / 0	9126	Please ensure that the site plan you have is the most current, approved plan and is the same as the one MNR has on file.							
Is the site held in reserve? YES or NO										
Copies of Report Sent to: County/Regional Municipality Local Municipality Ministry of Natural Resources										
(by Se	eptember 30th)		☑ YES	☑ YES	☑ YES					
TO BE COMPLETED BY PERSON CONDUCTING REVIEW (Including on-site inspection)										
Date Inspected: Y/M/D 2018 / 08 / 28 Review Conducted by: (Please Print) Amarjit S. Sandhu Signature (if different than licensee):										
Name of Company and	d Address: Pro-Insp	ect, 10 Da	vey Crescent, A	mherstview ON K7	N 1X6 Tel. 613-384-7067					
Position with Company: Principal										
Signature of Licen	see or Authorized O	fficial:								
Mike the Breton										
FOR MNR OFFICE USE ONLY										
Accepted by MNR: (✓ o	ne) YES I NO I	Date Accepted Y / M /		MNR Signature:						
Field Audit by MNR: (✔ o	ne) YES I NO	Date inspected Y / M /		MNR Signature:						
Follow up Notice Requir	red? YES N	10 🗖		Licence ID #:						

- Pursuant to Subsection 57(4) of the ARA, it is an offence to furnish false information.
- You must provide a sketch if remedial action is required or progressive rehabilitation has been performed.
- In order to extend the 90-day remedial action deadline date, you <u>must</u> obtain the Aggregate Inspector's approval (in writing) <u>prior to filing the report</u> with the Inspector or local MNR office.
- Please submit this report to the local Aggregate Inspector who administers your site, or the local MNR office.

(NOTE: ALL INFORMATION IN RESPECT OF THIS REPORT IS AVAILABLE FOR PUBLIC REVIEW)

ID 624984 - CBM Codrington Pit

